

marantz®

Video Conversion, AV Receivers, 2008 & 2007 models

SR6001
SR7002 / SR7001
SR8002 / SR8001

- ✓ Full up-conversion from composite video to HDMI
- ✓ Full down conversion from Component video to Composite

SR5002 / SR5001
SR9600

- ✓ Up-convert Composite video to S-video and Component video
- ✓ Down-convert S-video to Composite video

SR4002 / SR4001

- ✓ Up-convert S-video to Component video
- ✓ Down-convert S-video to Composite video

The SR301 and SR3001 do not offer a video conversion function

Note: Video conversion does not function for multi-zone video outputs. Composite video must be input to feed multi-zone composite video outputs (SR7001, SR7002, SR9600, SR8001, SR8002). Component video must be input to feed multi-zone component video outputs (SR8001, SR8002).

If you have further question, please contact



24 Lionel Road, Mt Waverley, VIC, 3149
Phone: 03 8542 1111
Email: sales@qualifi.com.au